

SECTION 9

Pilot's Operating Handbook Supplement AS-10

Garmin GMA 350 Audio Panel



This supplement is applicable and must be inserted into Section 9 of the Pilot's Operating Handbook when a Garmin GMA 350 Audio Panel is installed in the AQUILA AT01-100. The information in this supplement adds to or replaces information in the basic Pilot's Operating Handbook.

Revision A.02 of AFM Supplement AS-10 ref. FM-AT01-1010-249 is approved under the authority of DOA ref. EASA.21J.025.


 15.10.2013
 Date, Signature Office of Airworthiness

| Document Nr.: | Issue: | supersedes Issue: | Date: | Page: |
|------------------|--------|-------------------|------------|---------|
| FM-AT01-1010-249 | A.02 | 28.05.2013 | 15.10.2013 | AS-10-1 |

0.1 RECORD OF REVISIONS

| Issue | Reason for Change | Effectuated Pages | Date of Issue |
|-------|-------------------|-------------------|---------------|
| A.01 | Initial Issue | All | 28.05.2013 |
| A.02 | Editorial Changes | All | 15.10.2013 |
| | | | |

0.2 LIST OF CURRENT PAGES

| Page | Issue | Date |
|-------|-------|------------|
| 1 - 4 | A.01 | 28.05.2013 |
| 1 - 4 | A.02 | 15.10.2013 |
| | | |
| | | |
| | | |
| | | |

| Page | Issue | Date |
|------|-------|------|
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

0.3 TABLE OF CONTENTS

| | | |
|----|--|---|
| 1. | GENERAL..... | 3 |
| 2. | OPERATING LIMITATIONS | 3 |
| 3. | EMERGENCY PROCEDURES | 3 |
| 4. | NORMAL PROCEDURES | 3 |
| 5. | PERFORMANCE | 3 |
| 6. | WEIGHT AND BALANCE..... | 4 |
| 7. | SYSTEMS DESCRIPTION..... | 4 |
| 8. | HANDLING, SERVICE AND MAINTENANCE..... | 4 |

| Document Nr.: | Issue: | supersedes Issue: | Date: | Page: |
|------------------|--------|-------------------|------------|---------|
| FM-AT01-1010-249 | A.02 | 28.05.2013 | 15.10.2013 | AS-10-2 |

1. GENERAL

The aircraft is equipped with a GMA 350 Audio Panel.

For a detailed description and full operating instructions please refer to the current issue of the GARMIN GMA 350 Pilot's Guide, P/N 190-01134-12 (at least Rev. D).

| |
|-------------|
| NOTE |
|-------------|

The current issue of the GARMIN GMA 350 Pilot's Guide P/N 190-01134-12 (at least Rev. D) must be kept on board the aircraft and be available to the crew at all times.

2. OPERATING LIMITATIONS

The operating limitations of the basic POH apply without any changes or restrictions.

3. EMERGENCY PROCEDURES

Should the audio panel fail, the audio system automatically connects the pilot's head-set to COM 1, ensuring that he can continue to receive and transmit.

If necessary, the audio panel can be shut down by pulling the **AUDIO** circuit breaker.

4. NORMAL PROCEDURES

For a detailed description and full operating instructions, please refer to the current issue of the GARMIN GMA 350 Pilot's Guide, P/N 190-01134-12 (at least Rev. D).

| |
|----------------|
| CAUTION |
|----------------|

The GMA 350 must be switched off during engine start-up and shut-down with the Avionics Master Switch set OFF.

Non-compliance could destroy the system. All warranty and guarantee claims will become void.

5. PERFORMANCE

There is no change regarding the information in the basic Pilot's Operating Handbook.

| Document Nr.: | Issue: | supersedes Issue: | Date: | Page: |
|------------------|--------|-------------------|------------|---------|
| FM-AT01-1010-249 | A.02 | 28.05.2013 | 15.10.2013 | AS-10-3 |

6. WEIGHT AND BALANCE

There is no change regarding the information in the basic Pilot's Operating Handbook.

7. SYSTEMS DESCRIPTION

Functions and Operation

The GMA 350 Audio Panel offers the classical selection functions for microphone and receiver. In addition, it includes an intercom system (ICS), a marker beacon receiver and a COM recorder.

For a detailed description and full operating instructions, please refer to the current issue of the GARMIN GMA 350 Pilot's Guide, P/N 190-01134-12 (at least Rev. D).

Electrical protection for the GMA 350 Audio Panel

The GMA 350 is attached to the avionics bus and can be shut down by pulling the circuit breaker **AUDIO**.

8. HANDLING, SERVICE AND MAINTENANCE

There is no change regarding the information in the basic Pilot's Operating Handbook.

| <i>Document Nr.:</i> | <i>Issue:</i> | <i>supersedes Issue:</i> | <i>Date:</i> | <i>Page:</i> |
|----------------------|---------------|--------------------------|--------------|--------------|
| FM-AT01-1010-249 | A.02 | 28.05.2013 | 15.10.2013 | AS-10-4 |